

BUILDING-STRUCTURE INVENTORY FORM

Site #25

For Office Use

Michigan History Division
Michigan Department of State
Lansing, Michigan 48918

Theme	_____

IDENTIFICATION

1. Building name Goyette's Home
2. County Oakland Town/City _____ Village Clarkston
3. Street Location 149 North Main Street
4. Ownership: a. Public b. Private
5. Present Owner Mr. & Mrs. Harold Goyette Address 149 North Main Street
6. Use: Original Home Present Home
7. Accessibility to Public: Exterior visible from public road: Yes No
Interior accessible: Explain Private Home

DESCRIPTION

8. Building Material a. clapboard b. stone c. brick d. board and batten
e. cobblestone f. shingles g. stucco h. other White aluminium siding
9. Structural Material a. wood frame with interlocking joints b. wood frame with light members (balloon frame)
c. masonry load-bearing walls d. iron frame e. steel frame with curtain walls
f. reinforced concrete g. other _____
10. Condition a. excellent b. good c. fair d. deteriorated
11. Integrity a. original site b. moved if so, when? _____
Notes on alterations and additions, with dates and architect. None Known

12. Related Outbuildings and Property

- a. barn b. carriage house c. garage d. privy e. shed
f. shop g. greenhouse h. landscape features i. other _____

13. Surroundings of the Building

- a. open land b. woodland c. scattered outbuildings d. densely built-up
e. commercial f. industrial g. residential h. other _____

14. Photo

15. Map

Site #25

16. Interrelationship of Building and Surroundings Blends well in its well landscaped lawn with the older trees and homes of the same era.

17. Other Notable Features of Building and Site A typical old farm home with the back boundary line on the Historic Mill Pond.

18. Threats to Building

a. none known b. zoning c. roads d. developers e. deterioration
f. other _____

SIGNIFICANCE (Indicate sources of information for all statements)

19. Architectural Significance

Date of Construction c. 1869 Architect _____

Builders, suppliers, etc. _____

Notes on original plan and specifications:

20. Historical Significance: John Davidson or Davison owner in 1869
George Van Syckle owner in 1872 ←
Frank King owner in 1908

21. Sources (for primary and secondary sources, give complete facts of publication: author, title, place of publication, date):

1872 Map of Clarkston, Atlas of Oakland County, F.W. Beers, N.Y., N.Y.; 1872
Tax Assessment Books located in the Village Hall, 25 S. Main Street

Prepared by Betty Galligan Date December 10, 1975
Address 25 S. Main Street Telephone 625-1559
Organization Clarkston Historical Society