

**BUILDING-STRUCTURE INVENTORY FORM**

Michigan History Division  
Michigan Department of State  
Lansing, Michigan 48918

For Office Use

Theme \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

**IDENTIFICATION**

1. Building name Henry Woolfenden residence
2. County Oakland Town/City \_\_\_\_\_ Village Clarkston
3. Street Location 99 N. Main St.
4. Ownership: a. Public  b. Private
5. Present Owner Henry Woolfenden Address 99 N. Main
6. Use: Original residence Present residence
7. Accessibility to Public: Exterior visible from public road: Yes  No   
Interior accessible: Explain no

**DESCRIPTION**

8. Building Material a. clapboard  b. stone  c. brick  d. board and batten   
e. cobblestone  f. shingles  g. stucco  h. other \_\_\_\_\_
9. Structural Material a. wood frame with interlocking joints  b. wood frame with light members (balloon frame)   
c. masonry load-bearing walls  d. iron frame  e. steel frame with curtain walls   
f. reinforced concrete  g. other \_\_\_\_\_
10. Condition a. excellent  b. good  c. fair  d. deteriorated
11. Integrity a. original site  b. moved  if so, when? \_\_\_\_\_  
Notes on alterations and additions, with dates and architect.  
extensive alterations to exterior and interior about 1930 by architects Ward and Baumgartner (see xeroxed material). Slab and screened porch added in 1941, changed to room 1947. 1965, garage lengthened, breezeway changed
12. Related Outbuildings and Property a. barn  b. carriage house  c. garage  d. privy  e. shed   
f. shop  g. greenhouse  h. landscape features  i. other \_\_\_\_\_  
patio and view of Mill Pond
13. Surroundings of the Building a. open land  b. woodland  c. scattered outbuildings  d. densely built-up   
e. commercial  f. industrial  g. residential  h. other \_\_\_\_\_
14. Photo \_\_\_\_\_ 15. Map \_\_\_\_\_



16. Interrelationship of Building and Surroundings

This residence is one of many lovely old homes on the Main St. of Clarkston.

17. Other Notable Features of Building and Site

During the 1930 ~~rest~~ remodeling beautiful millwork was used throughout the house. There are lovely ~~ceiling~~ moldings, doorframes, banisters, fireplaces (two). Brass hardware is used throughout and a Williamsburg lock on the front door.

18. Threats to Building

- a. none known  b. zoning  c. roads  d. developers  e. deterioration   
f. other Main Street may be widened

**SIGNIFICANCE** (Indicate sources of information for all statements)

19. Architectural Significance

Date of Construction about 1905 Architect \_\_\_\_\_

Builders, suppliers, etc. \_\_\_\_\_

Notes on original plan and specifications:

see attached articles for the remodeling by Mrs. Waterbury  
The stone basement has not been changed under the living room, dining room, library and front hall.

20. Historical Significance:

The house itself has no historical value since it began as a Victorian home and was changed into an attractive colonial. However it is on the Main St. of Clarkston and part of the area we hope will become a historic village.

21. Sources (for primary and secondary sources, give complete facts of publication: author, title, place of publication, date):

article in Clarkston News about 1935 on remodeling of the Waterbury House  
Helen and Henry Woolfenden, 99 N. Main St. Clarkston  
Mrs. James Glennie, 6570 Cranberry Lk. Rd., Clarkston (daughter of previous owner)

Prepared by Mary W. Huttenlocher Date Nov. 24, 1975

Address 6757 Parke Lake Dr. Clarkston Telephone 625 1627

Organization \_\_\_\_\_